## **CLAY INDEX** TEST REPORT



Project:

Investigation for Quarry Manager

Location:

Wood Rd (Kara) Quarry

Client:

United Quarry Ltd

Contractor:

N/A

Sampled by:

I.C.Twichel 25/07/23

Date sampled: Sampling method:

NZS4407:2015 Part 2.4.6.3.2

Sample description:

GAP40

Sample condition: Source:

Crushed Stockpile at Quarry Project No:

117109.00

Lab Ref No:

WL3187 CI

Client Ref No:

Test Results

Clay index:

3.2

Test Method

NZS 4407: 2015, Test 3.5

Date tested: 27/07/23

Date reported: 02/08/23

Sampling is covered by IANZ Accreditation

This report may only be reproduced in full

Approved Signatory

Designation:

Laboratory Manager

02/08/23 Date:

CCREDITES

All tests reported herein have been performed in accordance with the laboratory's scope of accreditation

PF-LAB-050 (19/01/2022)

PO Box 553, 0140, Whangarei, New Zealand

Page 1 of 1

WSP

Whangarei (Port Rd)

Quality Management Systems Certified to ISO 9001

Telephone +64 9 4301 723 Website www.wsp.com/nz